



ENVIROSEAL™

Stabilize and Seals the Two Mile Running Track at New York's Central Park - July / August 1997

THE PROBLEM : DUST AND NO STABILIZATION



The pictures to the left and above were the general condition when we started the job. The track was not used to it's full capability, was full of potholes, poor drainage, and frequent wash-boarding



We spread a (4) four inch layer of 1/4" minus material with a tow-behind asphalt spreader. The aggregate was then sprayed at a mix ratio of 3:1 water and Enviroseal till saturated.



ENVIROSEAL™

New York's Central Park Revisited

STILL NO DUST AND FULLY STABILIZED AFTER MORE THAN (5) FIVE YEARS



The photo to the left was taken in September of 1999 after countless MILLIONS of runners, walkers and joggers had traveled this trail. It is obvious that the track had survived it's five (5) winters and held up extremely well. It has been reported that The City is very pleased with the condition as well as the many runners we interviewed. The cost savings in maintenance and replacement have been substantial.

The photo to the right was taken in August of 2000. As you can plainly see, the track is still in excellent condition. The City is still more than pleased and the runners are ecstatic. The cost savings to the City are many thousands of dollars. All Of This With Very Little Maintenance For Five (5) Years Now.
How Much Can We Save You ??



**YOU CAN NOW ORDER A POWERPOINT CD BY CONTACTING
US BELOW FOR THIS AND OTHER TRAIL PROJECTS**

PROVEN TRAIL / TRACK ADA DESIGN BY

ENVIROSEAL CORP
1019 SE Holbrook Ct.
Port St. Lucie, FL 34952
Phone: 772-335-8225 Fax: 772-335-3991
Toll Free: 800-775-9474
email: sales@enviroseal.com
web: www.enviroseal.com